

List of errors

Code	Fault description	Code	Fault description	Code	Fault description
E01	Error reaching boiler level	W02	Failure to read Group 2 flowmeter	W37	EV line cold water economiser short circuit
E02	Boiler pressure not reached	W03	Failure to read Group 3 flowmeter	W38	EV line hot water economiser interruption
E03	Boiler level probe short circuit	W08	Maintenance warning	W39	EV line hot water economiser short circuit
E04	Boiler level probe interruption	W20	EV line water supply interruption	W44	EV line group 1 profiling interruption
E05	IDS connection missing	W21	EV line water supply short circuit	W45	EV line group 1 profiling short circuit
E06	Resin regeneration failure	W22	EV line drain interruption	W46	EV line group 2 profiling interruption
E07	Maintenance failure	W23	EV line drain short circuit	W47	EV line group 2 profiling short circuit
E08	Washing failure	W24	EV line group 1 interruption	W48	EV line group 3 profiling interruption
E09	5 V connection services missing	W25	EV line group 1 short circuit	W49	EV line group 3 profiling short circuit
E10	Pressure transducer connection missing	W26	EV line group 2 interruption	W70	Lighting group 1 interruption
E11	12 V connection services missing	W27	EV line group 2 short circuit	W71	Lighting group 1 short circuit
E12	12 V power board connection missing	W28	EV line group 3 interruption	W72	Lighting group 2 interruption
E13	24 V connection power valves missing	W29	EV line group 3 short circuit	W73	Lighting group 2 short circuit
E14	24 V connection display unit missing	W32	EV line left steam interruption	W74	Lighting group 3 interruption
E15	24 V Triac connection missing	W33	EV line left steam short circuit	W75	Lighting group 3 short circuit
E19	Boiler over pressure	W34	EV line right steam interruption	W92	Cup warmer 1 temperature probe interruption
E20	Boiler safety level intervention	W35	EV line right steam short circuit	W93	Cup warmer 1 temperature probe short circuit
W01	Failure to read Group 1 flowmeter	W36	EV line cold water economiser interruption	W96	External temperature probe group 1, interruption

List of errors

Code	Fault description	Code	Fault description	Code	Fault description
W97	External temperature probe group 1, short circuit	W149	Internal temperature probe set-point, group 1, not reached	W220	EV line right steam interruption
W98	External temperature probe group 2, interruption	W150	Internal temperature probe overheating group 2	W221	EV line right steam short circuit
W99	External temperature probe group 2, short circuit	W151	Internal temperature probe set-point, group 2, not reached	W222	EV line left cold water economiser
W100	External temperature probe group 3, interruption	W152	Internal temperature probe overheating group 2	W223	EV line cold water economiser short circuit
W101	External temperature probe group 3, short circuit	W153	Internal temperature probe set-point, group 3, not reached	W224	EV line hot water economiser interruption
W104	Internal temperature probe group 1, interruption	W156	Maintenance warning	W226	EV line group 1 profiling interruption
W105	Internal temperature probe group 1, short circuit	W200	EV line water supply interruption		
W106	Internal temperature probe group 2, interruption	W201	EV line water supply short circuit		
W107	Internal temperature probe group 2, short circuit	W202	EV line drain interruption		
W108	Internal temperature probe group 3, interruption	W203	EV line drain short circuit		
W109	Internal temperature probe group 3, short circuit	W206	EV line group 1 interruption		
W140	External temperature probe overheating group 1	W207	EV line group 1 short circuit		
W141	External temperature probe set-point, group 1, not reached	W208	EV line group 2 interruption		
W142	External temperature probe overheating group 2	W209	EV line group 2 short circuit		
W143	External temperature probe set-point, group 2, not reached	W210	EV line group 3 interruption		
W144	External temperature probe overheating group 3	W211	EV line group 3 short circuit		
W145	External temperature probe set-point, group 3, not reached	W212	EV line left steam interruption		
W148	Internal temperature probe overheating group 1	W213	EV line left steam short circuit		